

Preface

The LABS Methodology & Standards are developed by qualified engineers, based on international best practices and codes such as NFPA, IBC and others, as well as experiences from Bangladesh. Also, in accordance with the spirit and intent of the respective country standards.

Under LABS, in addition to applicable country laws, factories commit to adhering to a harmonized, country level standard around Structural, Fire, Electrical safety.

However, due to some **challenges faced** during the remediation action, such as **space constraints**, **structural challenges**, **unplanned initial construction**, **rented premises**, **financial difficulties**, **etc**. some factories are unable to proceed with Remedial activities and in such cases, **LABS team assists** the factories with alternate remediation options **in consultation with the Inspection firm** assessors, which still falls under the purview of the Safety standards.


This document captures examples of such **Alternate solutions** provided to factories on a case-to-case basis.





Issue/Description: Incomplete separations of different occupancies

Original issue image



CAP: Provide 1-hour fire rated partition wall with 45-minute self-closing fire rated doors between occupant areas

Applicable standards: Cl. 3.10 and Cl. 3.11 of the Labs Standard and LABS Methodology 5.3.2.3.

Remediation Image



Primary Solution: Separate storage areas from adjacent areas by means of 1-hour fire rated construction (including the fire rated wall and fire rated doors)

Design approval required: Yes

Alternate remediation image



Alternate Solution 1: Separate storage areas from adjacent areas by Drencher system (water curtain). The design of the water supply system is needed (including pump capacity, water storage, etc.)





Issue/Description: Incomplete separations of different occupancies


Original issue image



CAP: Provide 1-hour fire rated partition wall with 45-minute self-closing fire rated doors between occupant areas

Applicable standards: Cl. 3.10 and Cl. 3.11 of the Labs Standard and LABS Methodology 5.3.2.3.

Remediation Image



Alternate Solution 2: To restrict the spread of fire, the in-process temporary storage (<25% floor area) should be arranged in order to compliance with LABS standard (Apply for Non-sprinkler area)

Design approval required: No

Alternate remediation image



Alternate Solution 3: To restrict the spread of fire, the in-process temporary storage (<25% floor area) should be arranged in order to compliance with LABS standard (Apply for Sprinkler area)





Issue/Description: Unless in-rack automatic sprinklers have been designed and installed, solid shelf racking shall not be used

Original issue image



CAP: Unless in-rack automatic sprinklers have been designed and installed, solid shelf racking shall not be used. A minimum of 50% openings in shelving material shall be considered open shelves.

Applicable standards: LABS standard Cl 5.3.8.2

Remediation Image



Primary Solution: In-rack automatic sprinklers installed

Design approval required: Yes

Alternate remediation image



Alternate Solution 1: Open Rack with more than 50% opening holes





Issue/Description: Unless in-rack automatic sprinklers have been designed and installed, solid shelf racking shall not be used

Original issue image



CAP: Unless in-rack automatic sprinklers have been designed and installed, solid shelf racking shall not be used. A minimum of 50% openings in shelving material shall be considered open shelves.

Applicable standards: LABS standard CL 5.3.8.2

Remediation Image



Alternate Solution 2: Separated the solid shelves to the single solid panels with areas less than 1.9m2 and maintain the flue space 150mm.

Design approval required: Yes

Alternate remediation image



Alternate Solution 3: Maintain the transverse flues 150mm at maximum 1.5m interval





Issue/Description: The sprinklers were installed far below the ceiling (>300mm)

Original issue image



CAP: The distance between the sprinkler deflector and the ceiling shall be a minimum of 1 in. (25 mm) and a maximum of 12 in. (300 mm) throughout the area of coverage of the sprinkler.

Applicable standards: According to NFPA13 CL8.6.4, TCVN 7336-2003 Cl 6.6

Remediation Image



Primary Solution: The sprinkler heads have been moved close to the roof (<300mm).

Design approval required: Yes

Alternate remediation image




Alternate Solution: The pendant ceiling has been installed to cover the sprinkler area.





Issue/Description: Fire rated separation between multiple occupancies


Original issue image



CAP: Fire rated compartmentation to be provided between 2 different occupancies to avoid the spread of fire from one area to the other

Applicable standards: According to LABS Cl. 3.14.

Remediation Image



Primary Solution: Construction of Fire rated separation with brick and mortar to enable a 2-hour fire rated protection

Design approval required: Yes

Alternate remediation image



Alternate Solution: Where maintaining structural load to under lying floors is a challenge, Fire rated enclosure provided using Aerocon panels instead of civil wall structure.





Issue/Description: In-adequate water storage for fire-fighting


Original issue image



CAP: Inadequate fire water tank of only 50,000 litre underground with negative suction for firefighting.

Applicable standards: According to LABS Cl. 5.8

Remediation Image



Primary Solution: Provide fire water tank with additional 100,000 litre capacity for firefighting purposes during emergencies.

Design approval required: Yes

Alternate remediation image



Alternate Solution: Modular fire water tank provided instead of underground civil structured water tank where there is no space constraints along with positive suction for delivery header.





Issue/Description: Fire rated separation to be provided for lift lobby

Original issue image



CAP: Lack of fire rated enclosure for lift lobby connecting more than two floors.

Applicable standards: According to LABS Cl. 4.8

Remediation Image



Primary Solution: Provide fire rated enclosure for lift lobby by installing 120 min fire rated door and along with civil wall structure for lobby enclosure.

Design approval required: Yes

Alternate remediation image



Alternate Solution: Provide fire curtain for lift lobby along with integration of curtain with fire alarm system where there is a space constraint to construct a fire rated wall.





Issue/Description: Lack of column bracing of the steel building


Original issue image



CAP: Missing column bracings were observed for buildings.

Applicable standards: Refer to Clause 8.5 and 8.18 of the LABS Standard

Remediation Image



Primary Solution: Provide the X column bracing as design.

Design approval required: Yes

Alternate remediation image



Alternate Solution: Provide the frame bracing where the door located





Issue/Description: Fire suppression system for electrical panels in operational/escape path areas.

Original issue image



CAP: Electrical panels and other installations were found in the exit staircases in the factory.

Applicable standards: According to LABS Cl. 6.14.4

Remediation Image



Primary Solution: Separate the electrical panels and installation by providing fire rated enclosure of 120 min fire rated door and along with civil wall structure for lobby enclosure.

Design approval req'd: Yes

Alternate remediation image



Alternate Solution: Provide fire suppression system for electrical panels and installation in production and escape path areas along with integration to fire alarm system.





LABS Data Repository

- 1. LABS Toolkit
- 2. Good practice session presentations
- 3. Mainstreaming Gender Equality In Safety Procedure
- 4. LABS remediation action flow CAP Sign-off, Design approval and CAP Closure
- 5. LABS Standards and Methodology



