



LABS

Life And Building Safety

LABS - GOOD PRACTICES SHARING

3rd May 2024

AGENDA

Time	Contents	PIC
2:00PM - 2:15PM	Welcome & Introduction – 15'	LABS/Brands
2:15PM - 2:30PM	LABS Assessment & Remediation Review – 15'	LABS
2:35PM – 2:40PM	Process for effective remediation 5'	LABS
2:40PM - 3:15PM	Good Practices Sharing – 45'	LABS
3:15PM - 3:25PM	Q&A – 10'	Factories
3:25 PM – 3:40 PM	LABS Graduation – 15'	LABS
3:40 PM – 03:50PM	Update on LABS helpline-10'	LABS
3:50PM - 4:00PM	Closing – 10'	LABS

WELCOME & INTRODUCTION



Life and Building Safety Initiative (LABS)

Promoting a safe and secure working environment in the apparel and footwear industry



The **Life and Building Safety (LABS) Initiative** is an industry-driven program, in which multiple brands and retailers are joining forces with public organizations to operate a scalable program to eliminate preventable **structural, fire and electrical safety risks** in key apparel and footwear producing countries in a targeted way.

Life and Building Safety Initiative (LABS)

LABS organizes activities around identifying and solving risks related to:



Fire safety



Electrical safety



Structural safety

VIETNAM



INDIA




CAMBODIA



INDONESIA



Assessment & Remediation Phases




Phase

4

Graduated factories will be required to undergo **self-assessment twice a year** by filing the self-assessment checklist. LABS team will review the checklist and in case of any deviations identified, the information will be communicated to the respective brand participants along with the recommendations for factory to enrol back into the LABS Program.

Remediation Process



CAP Closure by Inspection firm

Remediation Completed by factory team in lines with agreed Design of CAP

Design sign off between IF and Factory Team


Factory started Remediation as per agreed CAP and starts preparing Design

CAP sign off Between IF and Factory team to review course of action for remediation of issues Identified


Factory starts reviewing issues and preparing corrective actions respectively

Factory are suggested to start working on graduation preparation parallely with remediation for implementation of Safety management system

What factory should do for effective and faster remediation



Hierarchy of Risk Control



Remediation Example



Index

1. Fire Compartmentation

1. Staircase Compartmentation
2. Fire separation of occupancies
3. Self-closing Fire rated door

2. Fire detection system

1. Smoke detection system
2. Fire Alarm system
3. Smoke detector positioning

3. Fire Suppression system

1. Fire pumps
2. Sprinklers system
3. Water storage capacity

4. Exit Doors

1. Locking mechanism
2. Rolling shutters

5. Earthing and bonding

1. Equipotential Bonding
2. Earthing connection
3. Earth Pit
4. Earth pit drawings

6. Electrical Distribution

1. Current carrying capacity
2. Lint & Dust
3. Lugs & Gland

7. Substations & Generators

1. Danger Notice & warning Signs
2. Separation from occupancies
3. Servicing and maintenance

8. Structure maintenance

1. Corrosion
2. Dampness and water egress
3. Cracking

9. Distress in structure

1. Column stress
2. Seismic bracing
3. Torsion

10. Structure load management

1. Allowable load plan
2. Uncontrolled loading
3. Soil report

Fire compartmentation



- Lack of enclosure of Stairs connecting more than 2 floors.
- Unsealed penetrations in stair enclosures



- Absence of fire-rated doors in the main exit at the production building.
- Fire-rated self-closing doors are not provided at protected staircases.
- Factory Building has more than two floors and the FR self-closing doors are not found provided on the stairs.



- Boilers installed on 2nd floor with washing without enclosure.
- Designated storage areas not separated by FR construction.
- Transformer room at Building 2 without FR-rated construction.


Observation - Factory Building has more than two floors and the enclosure for stairs is not found provided.

CAP- Provide an enclosure in staircase that conceals all openings with fire-rated material to ensure the safety.

Design sign-off required – Yes, Approval has been granted to the Factory for the fire door design. Additionally, the process of sealing window openings in the staircase has been approved.



Staircase compartmentation with Fire doors



Staircase compartmentation with Fire doors & Brick work

Remediation- The factory has replaced the normal doors with self-closing, fire-rated doors and sealed openings with brick walls

LABS standard reference-: Refer Part 4 fire protection construction(Pg 23)

Observation- The boiler is installed on the terrace in a tin shed enclosure with no Fire Rated Separation with canteen on the same floor.

CAP- Provide separate enclosure with fire-rated material of up to 120 min resistance to ensure if any incident occurs in boiler it can be contained.

Design sign-off required – Yes, Approval has been granted to the Factory for the fire enclosure



Boiler enclosure by Fire rated material and fire door



Panel room enclosure by fire door

Remediation- The factory has replaced the normal doors with self-closing, fire-rated doors and sealed openings with brick walls/fire rated material

LABS standard reference-: : Refer 3.13 & 3.14 Use and Occupancy (Pg 14)

Observation- Fire-rated self-closing doors are not provided in any of the exits leading to staircase

CAP- Emergency exit to be provided with self-closing fire-rated door as per IS 3614

Design sign-off required – Yes, Approval has been granted to the Factory for the Self closing fire doors



Self-closing Fire door



Self-closing Fire door

Remediation- The factory has replaced the normal doors with self-closing, fire-rated doors.

LABS standard reference-: Refer standard 4.5(Page no -25) for more details about fire doors.

Fire detection system



- Inadequate Fire Detector coverage.
- The provided smoke detection system is insufficient to cover the entire area of the factory.



- Audible alarms with less volume observed in the basement and ground floor.
- Fire Alarm System were not installed in few locations.



- Detectors are installed at low level from the true ceiling.
- Incorrect fire detector positioning was found at some places.


Observation - Factory basement section, Nort-East does not have any coverage of smoke detector .

CAP- Smoke detection coverage would be provided in every location.

Design sign-off required – Yes, Approval as per smoke detector specification and drawing specifying installation points in floor layout would be provided.



Smoke detector installed



Smoke detector layout Plan

Remediation- The factory has installed a smoke detector synchronized with fire alarm panel.

LABS standard reference-: Refer Part 5.10 Automatic Fire Detection and Alarm System (Pg 33)

Observation — Fire alarm was feeble or not audible in basement.

CAP- To improve the audibility of the fire alarm, an additional fire alarm will be installed.


Design sign-off required — No, Approval is not required for installation of fire alarms



Extra hooters are added near exits



Visual hooters are added in utility area



Extra hooters are added in floor

Remediation- The factory has installed extra hooters to enhance the audibility of alarm system.

LABS standard reference-: Refer Part 5.10 Automatic Fire Detection and Alarm System (Pg 33)

Observation — Smoke detector positioning was inadequate and found installed below ceiling level.

CAP- Smoke detector would be installed over the highest and flat part of ceiling .

Design sign-off required — No, if required Approval as per smoke detector specification and drawing specifying installation points in floor layout would be provided.



Beam type smoke detector installed for high roof



Smoke detector positioning before and after

Remediation- The factory has installed beam type smoke detector over ceiling more than 20 feet and replaced smoke detector to the highest point of the ceiling in 14 ft ceiling.

LABS standard reference-: Refer Part 5.10 Automatic Fire Detection and Alarm System (Pg 33)

Fire Suppression System



- Absence of fire pumps in the installed fire water line at the premises.
- Pump-set back-up not provided
- Only single fire pump installed for fire-fighting purpose.
- Diesel backup fire pump not provided.



- Insufficient water storage on premises for firefighting systems.
- Only 10 KL dedicated water available for fire fighting.



- A Non-Sprinklered storage area exists with excessive storage and is not effectively separated by FR separation with production areas.
- No fire-rated compartmentation is provided between the non-sprinklered storage area.

Observation — Only single fire pump installed for fire-fighting purpose. .

CAP- Ensure adequate fire pumps with electric and non-electric backup for firefighting.

Design sign-off required — Yes, Design specification of pumps and their efficiency is reviewed during design sign off.



All 3 Fire pumps are installed



Backup Fire pumps are installed

Remediation- The factory has installed 3 fire pump jockey pump, main pump and diesel powered pump in the premises.

LABS standard reference-: Refer Part 5.8.2 installation of fire pumps as per IS 15301(Pg 32)

Observation — Insufficient water storage on premises for firefighting systems.

CAP- Will ensure that the factory has a water capacity of 1.5 lakh litres specifically for fire-fighting purposes.

Design sign-off required — Yes, the Design specification of tanks its installation needs to be reviewed by structural and fire accessors.



Additional water tanks installed by factory



Underground water tank constructed

Remediation- The factory has installed additional water tanks, either overhead or underground, to address the issue of water shortage.

LABS standard reference-: Refer Part 5.8 water supply (Pg 32)

Observation — A Non-Sprinklered storage area exists with excessive storage and is not effectively separated by FR separation with production areas.

CAP- Provide sprinkler system in storages areas .

Design sign-off required — Yes, the Design specification of the sprinkler need to be reviewed by fire accessor.



Additional water tanks installed by factory



Sprinklers installed in material store

Remediation- The factory has installed sprinklers in storage areas.

LABS standard reference-: Refer to Part 3.15.4 water supply (Pg 22)

Exit doors



- Exit doors in the factory have locking devices /have rolling shutters with the locking mechanism.
- Exit doors not side hung to swing correctly in the direction of escape.
- Lockable device installed over exit door from outside.

Observation — The factory exit door is equipped with a locking mechanism and a rolling shutter.

CAP- All rolling shutters will be removed with outward opening doors for safe evacuation.

Design sign-off required — No Design sign is not required for this issue.



Rolling shutter has been removed



Fire door has been installed

Remediation- The factory has installed Fire rated door at the final door with push bar in place of shutter or have removed shutter.

LABS standard reference-: Refer Part 6.9 Automatic Fire Detection and Alarm System (Pg 43)

Observation — Lockable device installed on all exit doors from outside/inside .

CAP- Lockable device would be removed and locking arrangement would be revised.

Design sign-off required — No Design sign is not required for this issue.



Push bar has been install over doors



Rotating latch mechanism installed to bypass lock

Remediation- The factory has installed a fire-rated door with a push bar or mechanism that allows for bypassing the outside lock from the inside.

LABS standard reference-: Refer Part 6.9 Automatic Fire Detection and Alarm System (Pg 43)

Earthing and bonding



- Gate at the transformer yard is not looped with the fence for continuity of earthing
- Equipotential bonding (body earthing) to dissipate static charge not provided to Diesel day tank.



- Proper body earthing not evident in various distribution boards.
- Single body earthing provided to DG set.
- Earthing not provided to MS roof truss.



- Earth pits were found not maintained properly.
- Detail & layout plan of earth pit not available with the factory.

Observation — Bonding not provided over transformer gate/diesel tank .

CAP- Bonding will be provided over to dissipate charge safety from advised system.

Design sign-off required — No Design sign is not required for this issue.



Bonding provided over transformer gate



Bonding provided over LPG gas pipeline

Remediation- The factory has provided bonding to dissipate the static charge and to keep all conductors at the same potential.

LABS standard reference-: Refer Part 10.24 Earthing(Pg 84)

Observation — Body earthing not evident in distribution boards/Ms roof truss

CAP- Factory will identify missing earthing in panels and provide earthing as per electrical standards.

Design sign-off required — No Design sign is not required for this issue. Factory can request for design sign-off if they are designing new earthing grid for the factory.



double Earthing provided to transformer



Eearthing provided to MS truss

Remediation- The factory has installed copper strips for earthing in specific locations as a remedial measure.

LABS standard reference-: Refer Part 10.25 Earthing(Pg 84)

Observation — Earth pit were found poorly maintained/Earthing were found disconnected with earth strips

CAP- All earth pits will be maintained as per standard continuity check and resistance check will be carried out on same.

Design sign-off required — No Design sign is not required for this issue. Factory can request for design sign-off if they are installing new earthing pit .



Earth pit maintained and monitored

SHAHI EXPORT PVT. LTD E-10, Noida
Yearly Record Of Earth Resistance, Water & Salt Filling Schedule - YEAR - 2023


Sl. No	Location Of Earthing	No. Of Earthing	Earth Resistance (VVO)	Water & Salt Filling Schedule											
				May			Aug			July			Aug		
				A	B	C	A	B	C	A	B	C	A	B	C
1	330 KVA DG Body Earthing	2	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
2	200 KVA DG Natural Earthing	2	0.12	0.12	0.12	0.12	0.12	0.12	0.12						
3	500 KVA DG Body Earthing	2	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
4	500 KVA DG Natural Earthing	2	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
5	Busbar	2	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
6	Working Mch's	2	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
7	ETP plant	2	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
8	ET Plant Body Earthing	2	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
9	Transformer Body Earthing	2	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
10	Transformer Natural Earthing	2	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
11	Motor / VCB Room	2	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
12	Light Arrestor	0	0.15	0.15	0.15	0.15	0.15	0.15	0.15						
ELECTRICIAN SIGNATURE															
INCHARGE SIGNATURE															

Earthing continuity carried out by factory

Remediation- The factory maintained earth pit , the earth pit layout is developed & regular monitoring and testing records are actively maintained.

LABS standard reference-: Refer Part 10.25 Earthing(Pg 84)

Electrical distribution



- Proper identification markings were not provided on distribution boards.
- Cable current carrying capacity chart provided on distribution boards.



- Lint & Dust observed inside electrical panels.



- Cables were not terminated with proper lugs and glands
- Glands were missing inside the electrical panel, allowing access for insects.

Observation — Proper identification markings were not provided on distribution boards, and current carrying capacity not calculated.

CAP- Distribution board identification and current carrying capacity will be prepared .

Design sign-off required — No Design sign is not required for this issue.



Current carrying capacity calculated and posted over DB



Proper identification provided over panel

Remediation- The factory has provided proper identification over panel.

LABS standard reference-: Refer Part 10.8.14 Switchboard(Pg 76)

Observation — Lint & dust were observed inside the electrical panel.

CAP- Lint and dust would be cleaned and a monitoring plan would be set up.

Design sign-off required — No Design sign is not required for this issue.



Electrical panel has been cleaned



Electrical panel has been cleaned

Remediation- The factory has cleaned electrical panel and implemented a weekly checklist to prevent lint accumulation in panel.

LABS standard reference-: Refer Part 12.6 Housekeeping(Pg 90)

Observation — Cables were not terminated with proper lugs and glands.

CAP- Lugs and glands will be provided for electrical fitting.

Design sign-off required — No Design sign is not required for this issue.



Lugs provided for electrical panel



Glands provided over electrical panel

Remediation- The factory has provided lugs and glands in electrical panel.use of lugs and glands incorporated in SOP

LABS standard reference-: Refer Part 10.8.9 & 10.8.15 wiring in distribution board (Pg 77)

Substation and Generator



- Adequate warning/danger, voltage level signage were not posted over transformer, substation.

- Hazardous installations such as compressors, PNG skid, DG etc are found installed adjacent to the production floor or in exit route.



- Testing Report, Service record/maintenance record for Transformer and MV VCB MV/LV Switchgears were not available..

Observation – No proper danger or warning signage near HT meter room and transformer area.

CAP- Proper signage would be provided over electrical installation .

Design sign-off required – No Design sign is not required for this issue.



Sign age provided over substation



Warning signage provided

Remediation- The factory has provided warning signage over hazardous electrical installation.

LABS standard reference-: Refer Part 10.5.4.6 Layout of substation(Pg 73)

Observation — Hazardous installation installed adjacent to production with glass window towards production.

CAP- Separation need to be provided between production and high risk installation.

Design sign-off required — Yes Design is required is compartmentation is being provided.



Window opening towards compressors has been closed



Wall separation provided between transformer & evacuation route

Remediation- The factory has provided separation between hazardous installation and production.

LABS standard reference-: Refer Part 3.14.6,7 Separation of occupancies (Pg 17)

Observation — Testing Report, Service record/maintenance record for Transformer and MV VCB MV/LV Switchgears were not available.

CAP- Will provided 3rd part testing Checklist and maintain maintenance record of machines and installation .

Design sign-off required — No Design sign is not required for this issue.

CENTEX FABRICS EXPORT UNIT													
Transformer/Servo Checklist													
Month	Transformer Specification	Location	Checking date	Oil & Gas	Carrying	Proper	Insulation	Oil Level	Are Problem	Reserve	Remarks	Signature	
S.no	Code												
1													
2	(1)	Main Transformer	25/1/23	Clean	OK	OK	OK	OK	OK	NO		Ajay	
3													
4													
5													
6													
7	(2)	Servo	25/1/23	Clean	OK	OK	OK	OK	OK	NO		Ajay	
8													
9													
10													
11													
12	(3)	Servo	25/1/23	Clean	OK	OK	OK	OK	OK	NO		Ajay	
13													
14													
15													
16													
17													
18													
19													
20													

Verified Signature: *[Signature]* Authorized Signature: *[Signature]*

Sign age provided over substation

MATRIX CLOTHING PVT. LTD. (UNIT-197)			
DG(DIESEL GENERATOR) SET INSPECTION CHECK LIST			
Name By: <i>[Signature]</i>		Contract No. Name: <i>[Signature]</i>	
DG Identification Code: <i>[Signature]</i>		Date: <i>[Signature]</i>	
S.No.	SUBJECTS	Observation	Remarks
1	1. GENERAL INSPECTION & C.C.	YES/NO	
2	2. LOCATION	YES/NO	
3	3. CHECK CABLES ON LEAD	YES/NO	
4	4. FUEL SYSTEM	YES/NO	
5	5. FRESH WATER PUMP FOR WATER SUPPLY	YES/NO	
6	6. CHECK FUEL SUPPLY	YES/NO	
7	7. AIR SYSTEM	YES/NO	
8	8. CHECK AIR COLUMNS	YES/NO	
9	9. COOLING SYSTEM	YES/NO	
10	10. CHECK COOLANT LEVEL	YES/NO	
11	11. CHECK WATER TANKAGE	YES/NO	
12	12. CHECK OILS AND CORRECT	YES/NO	
13	13. CHECK BATTERY VOLTAGE AND WATER LEVEL	YES/NO	
14	14. CHECK BATTERY WATER LEVEL	YES/NO	
15	15. CHECK BATTERY CHARGE	YES/NO	
16	16. CHECK BATTERY THERMISTOR	YES/NO	
17	17. CHECK BATTERY ADJUSTMENT	YES/NO	

Warning signage provided

Remediation- The factory has maintained service record and checklist to monitor electrical installation.

LABS standard reference-: Refer Part 12.10 electrical maintenance(Pg 91)

Structure maintenance



- Significant corrosion making the structural element (beams, columns, truss) etc ineffective that may lead further structural damage.



- Dampness observed over Floor Roof and walls.



- Cracking observed over back side of building
- Cracks were observed over columns/beams

Observation — The structure element was found corroded.

CAP- Will review the corroded structure and repair it.

Design sign-off required — No Design sign is not required for this issue if factory wants they they get repair meathod review by structural accessor .



Corroded structure repaired and covered



Corroded bars were repaired from column

Remediation- The factory has repaired corroded structure members .

LABS standard reference-: Refer Part 8.25 maintenance(Pg 63)

Observation — wall cladding/backside wall observed for dampness

CAP- Factory will review structure with NDT test for impact of dampness over structure and repair dampness.

Design sign-off required — No Design sign is not required for this issue.



Dampness has been addressed



Dampness Repairs work has been done

Remediation- The factory has repaired dampness and removed leakages causing dampness.

LABS standard reference-: Refer Part 8.25 maintenance(Pg 63)

Observation — Cracks were observed on external wall/internal wall.

CAP- Will review cracks and get them repaired as per structural review.

Design sign-off required — No Design sign is not required for this issue.



Non structural cracks were repaired



SWATI STRUCTURE SOLUTIONS PVT. LTD.

Structural, Topography & Geotechnical Survey Consultants, Engineers & Project Management Consultant
H.O. : 503, Sachdeva Corporate Tower, Plot No. 8, Community Centre, Sector-8, Rohini, Delhi-110085
Ph. : 011-47528888, Mob. : 9811016049
E-mail : swaticonsultant@gmail.com, Website : <http://www.swatistructuresolutions.com>
GSTIN : 07AAKCS1882K1ZV, PAN No. : AAKCS1882K

TO WHOMSOEVER IT MAY CONCERN

The factory situated at Khasra no. 15/19&22, Village Begumpur, Khatola, Gurugram, Harayana was visited by our engineer on 04-03-2024. The said brick wall is a non-structural filler wall. The cracks visible are due to the poor construction methodology and workmanship, along with the wear and tear. The said cracks are repaired by introducing reinforcement to stitch the cracks and finish the area with Murga jaali, mortar and plaster.

Cracks survey report

Remediation- The factory has repaired cracks and initiated a structure audit to prevent reoccurrence of cracks

LABS standard reference-: Refer Part 8.25 maintenance(Pg 63)

Distress in structure



- Intermediate column stress check as jacketing work with steel angle section visible over column



- Seismic bracings are not provided for added MS structures as lateral support structural system.



- Goods Lift Side walls & 2nd floor External walls at North, West Side found to be inadequate to resist later forces


Observation — Intermediate column were observed stress due to overloading.

CAP- Factory has appointed the Structural Consultant and the consultant has provided the stability certificate for first floor and below the floor level.

Design sign-off required — Yes Design sign is required for this issue.



Jacketing provided for column level below



Stability certificate t

Remediation- The factory has assessed all column in building and provided jacketing of below column, verified through the structural engineer

LABS standard reference-: Refer Part 8.6 detail structural analysis(Pg 53)


Observation — Seismic bracings are not provided for added MS structures as lateral support structural system.

CAP- Factory to appoint a Structural Engineer to review the extent

Design sign-off required — Yes Design sign is required for this issue.



Bracing to MS structure



Survey report

Remediation- The factory has appointed structural consultant and provided bracing along with survey report

LABS standard reference-: Refer Part 8.17 Seismic bracing of key elements (Pg 58)


Observation — Goods Lift Side walls & 2nd floor External walls at North, West Side found to be inadequate to resist later forces.

CAP- Factory to appoint a Structural Engineer to review the extent

Design sign-off required — Yes Design sign is required for this issue.



Structural member has been reinforced



structural drawing of the Goods lift


Remediation- The factory has appointed structural consultant and provided support member in lift

LABS standard reference-: Refer Part 8.25 Application of NBC(Pg 51)


Observation — Finished Product -Fabric of height 2.13Mt Placed at SW corner of Factory at 2nd Floor without allowable load plans.

CAP- Factory to appoint a Structural Engineer to get load plans as per their structure

Design sign-off required — Yes Design sign is required for this issue.



Load plan



Load plan

Remediation- The factory has appointed structural for load plans and load is reviewed in every six months as per load plans


LABS standard reference-: Refer Part 8.9.3 Floor loading plans(Pg 55)

Q & A

LABS Graduation



Graduation verification



By following the graduation checklist, you can ensure the successful implementation of sustainable safety system in your factory. This comprehensive checklist outlines the necessary steps that need to be taken to create a safe and secure work environment

Expectation for Graduation

- To fulfill the graduation goals, it is the factory's responsibility to understand the requirements and develop a robust system to manage all aspects of the LABS graduation checklist based on their resources.
- To have a robust safety management system it is necessary to complete multiple PDCA cycle.
- Introducing the Safety procedure will not ensure effective management of safety unless and until its implementation has not been verified through several cycle.



Benefits of Safety Management System:

- Encourages safety culture
- Protects and enhances an organization's reputation and credibility
- Reflects business is socially responsible
- Maximize the performance and/or productivity of employees
- Increased employees' commitment to the team/organization
- More competent, happier and healthier workforce
- Reduces business costs and disruption
- Enables organizations to meet OHS expectations
- Workforce in general to stay longer in active life

COMPONENTS OF SMS:

- Safety Policy
- Safety Assurance
- Safety Risk Management
- Safety Promotion



Key Questionnaire - Ensuring to maintain defined safe load limit of floor and/or electrical circuits in case of any addition/removal of machinery, etc. as per design and drawings (such as single line diagram, as-built drawings etc.) approved by the competent authorities

Objective

To prevent hazards from current overflow and electrical short circuits, it is necessary to monitor and manage electrical loads according to approved guidelines and single line diagrams. To prevent hazards from current overflow and electrical short circuits, it is necessary to monitor and manage electrical loads according to approved guidelines and single line diagrams.

Process

It is important to develop a clear procedure that specifies responsibilities, timelines, processes, risks, and verification methods to ensure that jobs are carried out according to the specified process..

Electrical load
management
procedure

Checklist
implemented

Verification
protocol
implemented

Impact of safety management system

- Single line diagram has been bypassed.
- Factory load distribution might be imbalanced.
- High risk if short circuit.

Load plan has been developed

Before

Load plan has been developed and reviewed as per defined procedure/policy by Load manager

After

- Factory load is managed as per Approved design.
- No design change could be carried out without Load review.
- Life of electrical equipment increases.

LABS Helpline



LABS Helpline

LABS is introducing a mobile based chat platform along with helpline number where workers can reach out to LABS immediately and can report any safety related risk of their respective factories.

Kindly visit **labs-Chat.com** from the mobile browser and register your concern or scan QR code from LABS updated danglers and register your concern through LABS Chat



The graphic is a promotional poster for LABS Helpline. At the top left, it features a cartoon worker in a yellow vest and hard hat next to the text "YOUR SAFETY IS IN YOUR HANDS!". At the top right is the LABS logo, which consists of a red circular icon with concentric lines and the text "LABS Life And Building Safety". Below these is a red banner with white text that reads "Reach LABS Chat for immediate support!". The main body of the graphic contains instructions: "To register the case please use this link **labs-chat.com** or Scan the QR code from mobile Camera". A QR code is shown on the left, with a blue "SCAN" button below it. On the right, a hand is holding a smartphone displaying the LABS chat interface, which includes a "Chat with us" header and an "Ask Me" button. At the bottom right, it says "To reach Helpline, dial: **1800-212-5227**".

YOUR SAFETY IS IN YOUR HANDS!

LABS
Life And Building Safety

Reach LABS Chat for immediate support!

To register the case please use this link
labs-chat.com
or
Scan the QR code
from mobile Camera

To reach Helpline, dial:
1800-212-5227

SCAN



YOUR SAFETY IS IN YOUR HANDS!

Electrical issues can be life threatening. Be aware and report potential risks.



Multi looping of cables



Lint/dirt on electrical panel



Combustible material inside electrical panel

Reach LABS Chat for immediate support!

To register your concern please use this link
labs-chat.com

or
 Scan the QR code
 from mobile Camera



SCAN

To reach Helpline, dial:
1800-212-5227



YOUR SAFETY IS IN YOUR HANDS!

Fire issues can be life threatening. Be aware and report potential risks.



Blocked exit



Illuminated exit sign not provided over exit



Exit passage blocked by vending counter

Reach LABS Chat for immediate support!

To register your concern please use this link
labs-chat.com

or
 Scan the QR code
 from mobile Camera



SCAN

To reach Helpline, dial:
1800-212-5227



YOUR SAFETY IS IN YOUR HANDS!

Structural issues can be life threatening. Be aware and report potential risks.



Structural cracks



Unplanned/unsafe loading



Crack in the pillar

Reach LABS Chat for immediate support!

To register your concern please use this link
labs-chat.com

or
 Scan the QR code
 from mobile Camera



SCAN

To reach Helpline, dial:
1800-212-5227



Q & A

For further queries, contact : –

Ankith Hegde, Program Manager – hegde@labsinitiative.com

Rishi Ahlawat, Sr. Factory Coordinator – ahlawat@labsinitiative.com

Jayavardhan, Sr. Factory Coordinator – jayavardhan@labsinitiative.com

Madhu KA, Country manager - madhu@labsinitiative.com