# Quarterly

# News etter ( LABS Life And Building Safety





January 2021 Issue 1





**Factories onboarded** 

India: 43 Vietnam: 100



**Assessments conducted** 

India: 36 Vietnam: 77

Dear All.

We wish you and your loved ones a very happy new year!

The year 2020 will go down in history as the most unprecedented year this planet has yet to see. For the first time, it was unfathomable for us to predict where we were headed or what was on the horizon.

Though COVID-19 initially halted the rolling out of LABS processes, the program has seen considerable progress with sizeable numbers over the last quarter pertaining to process completion at factories. LABS Vietnam achieved the "100 factories onboarded" milestone, further strengthening our belief in the factories' acceptance of the LABS program; the progress is testimony to the collaborative success the LABS program has achieved through the years. It is imperative for all of us to collate our learnings and reflect on what is required by us in 2021 to transform and adopt the new normal, to evolve as individuals and leaders, and to operate businesses and relationships in this unsettled world. Please find below an overview of LABS' activities for last quarter.



Safety training conducted

India: 23 Vietnam: 60



340,359

Workers reached

India: 53,768 Vietnam: 286,591

## **IN THIS ISSUE**

- 1. 2020 Reflections
- 2. Operations Update Vietnam
- 3. Operations Update India
- 4. Quarterly Helpline Updates
- 5. Major Incidents in the Quarter
- 6. What the workers are saying

# 2020 Reflections

LABS onboarded over 140 factories in India and Vietnam in the year, including 100 factories in Vietnam.

Undeterred by pandemic-related challenges, LABS Initiative has maintained a steady state of operations in India and Vietnam throughout the year

Assessments completed at 77% onboarded factories

Safety trainings delivered at 78% assessed factories. Safety trainings now address new topics including COVID-19, related safety precaution and awareness, and good practices in health and hygiene

Delays in remediation were countered by conducting Corrective Action Plan (CAP) processes virtually and, as a result, the CAP has been signed off for 56% of assessed factories

# **Operations Update for the Quarter**

# **VIETNAM**

# 1. Assessments


LABS conducted 23 assessments and four Quality Assurance (QA) assessments during the quarter.

## **Factories assessed**

- BGG Lang Giang Garment Factory
   IBT Joint Stock Company Branch
- Texhong Thai Binh Garment Co., Ltd.
- Golden Star Joint Stock Company Limited - Quang Ninh Branch
- Nobland Vietnam Co., Ltd 2
- Sun Garment Textile Vietnam Co.,
   I td
- Manufacturing Sportswear Joint Stock Company - Thai Binh Branch - Factory No. 1 (MXP1)
- Manufacturing Sportswear Joint Stock Company - Thai Binh Branch - Factory No. 2 (MXP2)

- Manufacturing Sportswear Joint Stock Company - Thai Binh Branch - Factory No. 3 (MXP3)
- Manufacturing Sportswear Joint Stock Company - Thai Binh Branch - Factory No. 6 (MXP6)
- Manufacturing Sportswear Joint Stock Company - Thai Binh Branch - Factory No. 8 (MXP8)
- Star Fashion Company Limited
- Viet Thanh Garment And Trading Company Limited [Gia Binh Factory]
- Footgearmex Footwear Co., Ltd.


- Yi Feng Footwear Joint Venture Co., Ltd.
- Golden Star Company Limited, Stella
- Now Vina Co., Ltd.
- Pro Kingtex Vietnam Co., Ltd.
- G&G Fashion (Vietnam) Co., Ltd.
- QUANG VIET (LONG AN) Co., Ltd.
- Kwang Viet Garment Company Limited
- Pou Yuen Vietnam Co., Ltd. [D3]
- Hong Duong International Co., Ltd.
- An Hung Joint Stock Company An Thinh Factory



## Factories in which QA was conducted


- Appareltech Vinh Loc Garment Export Co., Ltd.
- Manufacturing Sportwear JSC Thai Binh Branch, Factory No. 6
- Now Vina Co., Ltd.
- Viet Thanh Garment And Trading Co., Ltd. Gia Binh Factory

# **Key Findings**




# **Fire Related Issues**

- Temporary obstacles on escape paths
- Lockable devices on many exit doors
- Doors in the means of egress not the side-hinged swinging type
- Fire-rated walls not designated between the production and storage areas



# **Electrical Related Issues**

- Cracks on the concrete elements (masonry walls, slab, beam)
- Uncontrolled load for the storage area on the mezzanine and first floors
- Corrosion on steel structures
- Missing bracings in the steel building



# **Structural Related Issues**

- · Cracks on the concrete elements (masonry walls, slab, beam)
- Uncontrolled load for the storage area on the mezzanine and first floors
- Corrosion on steel structures
- Missing bracings in the steel building



# 2. Remediations



# **Fire Safety:**

- 96% of the factories removed temporary obstacles on the evacuation pathways
- 68% of the factories provided additional illuminated exit signs at the exit doors
- 42% of the factories replaced shutter and sliding doors with side-hung doors
- 29% of the factories removed locking mechanisms from the exit doors



# **Electrical Safety:**

- 90% of the factories removed lint and dust from electrical panels and distribution boards
- 86% of the factories remediated the high temperature-related issues in electrical panels and distribution boards
- 83% of the factories provided backup power for emergency lighting and fire alarms
- 64% of the factories provided cable sockets/ferrules for cables



# **Structural Safety:**

- 48% of the factories remediated issues related to the vertical structural system
- 42% of the factories remediated issues related to the corrosion of steel elements
- 36% of the factories added or tightened bracings for the lateral structural system in their steel buildings

(Data given below is from 56 factories where 75 follow-up visits were conducted through December 31, 2020.)

# 3. Safety Trainings

# Safety-training sessions were provided for 31 factories this quarter

# Basic Level: \_\_

- Sees Vina Co., Ltd.
- CPPC Outdoor Wear (Vietnam) Co., Ltd.
- BGG Lang Giang Garment Factory - IBT Joint Stock Company Branch
- SSV Exports Garment Company
- Langham Garment Co., Ltd.
- Quang Viet (Tien Giang) Co., Itd.
- Hung Dat Shoes Co., Ltd.
- Ty Bach Co., Ltd.
- Yi Feng Footwear Joint Venture Co., Ltd.

# Level 1: -

- May Hai Joint Stock Company -Tan Lien Factory
- Nien Hsing (Ninh Binh) Garment Co., Ltd.
- Jia Hsin Co., Ltd.
- Shinwon Ebenezer Vietnam Co., Ltd.
- Youngone Nam Dinh Co., Ltd.
- Seshin Vn2 Co., Ltd.
- Viet Pan Pacific World Co., Ltd.

- Song Hong Garment JSC (Factory 3, 4, 5, 6)
- Nien Hsing (Ninh Binh) Garment Fulgent Sun Footwear Co., Ltd.
  - Song Hong Garment JSC Song Hong Nghia Hung Branch (Factory 15, 16, 17, 18
  - Exported Footwear Manufacturer; S&H Vina Co., Ltd.
  - Winners Vina Co., Ltd.
  - Texhong Thai Binh Garment Co., Ltd.

- Ngoc Hung Footwear Company
- Golden Star Joint Stock Company Limited - Quang Ninh Branch
- Now Vina Co., Ltd.
- Shinwon Ebenezer Ha Noi Co., Ltd.
- Sun Garment Textile Vietnam Co., Ltd.
- Footgearmex Footwear Co., Ltd.
- Star Fashion Company Ltd.

Level 2: Yakjin Vietnam Co., Ltd. -

A total of 621 people participated in the safety training sessions, with representatives from Factory Management, OHS Committee, HR and Maintenance department included electricians and security guards.

# INDIA

# 1. Assessments

LABS conducted five assessments and one Quality Assurance (QA) assessment during the quarter.

## Factories assessed:


- Celebrity Fashions
- · Celebrity Fashions Limited, MEPZ
- Jay Jay Mills India Pvt. Ltd.

- Texport Industries Pvt. Ltd.
- Texport Apparels LLP

## Factories in which QA was conducted


Celebrity Fashions Ltd., Narayanapuram

# **Key Findings**




# **Fire Related Issues**

- Non-sprinklered warehouse area had excessive storage and no fire-rated doors to separate from production area
- Lockable devices installed on exit doors
- Inadequate staircase widths
- Rolling shutters installed at emergency exits



## **Electrical Related Issues**

- Lightning protection system not installed at the building
- Earthing to battery bank rack and MS roof trusses not provided
- Electrical insulating mats missing in the vicinity of electrical panels
- Multiple hotspots with temperatures varying from 47\*C to 142\*C



# **Structural Related Issues**

- Visible cracks in structural members
- Concrete column with exposed, corroded steel bars
- Missing documentation (e.g. structural diagrams, geotechnical reports, single-line diagrams, floor-load plans)

# 2. Remediations



# **Fire Safety:**

- 53% of the factories installed emergency lights
- 72% of the factories removed temporary obstacles on the evacuation pathways
- 73% of the factories installed illuminated exit signages
- 35% of the factories removed locking mechanisms from exit doors



# **Electrical Safety:**

- 92% of the factories removed lint and dust from electrical panels and distribution
- 94% of the factories took necessary corrective action to reduce the high temperatures in the electrical panels and distribution boards
- 94% of the factories provided earthing connections for the electrical components



# **Structural Safety:**

- 47% of the factories remediated issues related to cracks in beams and columns
- 33% of the factories remediated corrosion in non-engineered structures, such as
- 60% of the factories remediated dampness in the walls

(Data given below is from 20 factories where 34 follow-up visits were conducted through December 31, 2020.)

# 3. Safety Trainings

# Safety-training sessions were provided for 12 factories this quarter

## Basic Level: \_\_\_\_\_

• Nahar Spinning Mills Limited

## Level 1: -

- Pee Empro Exports Pvt. Ltd. (Unit 78)
- Orient Fashions Exports (India) Pvt. Ltd. (Daffodils)
- Fashionage Corporation Pvt. Ltd. Venkateshwara Clothing Company (Unit-2)
  - Orient Craft Limited, Plot 9-13, Gurgaon
  - SMS Exports

- Pearl Global Industries Limited
- Matrix Clothing Pvt. Ltd. Unit 4
- Matrix Clothing Pvt. Ltd. Unit 2
- Texport Industries Pvt. Ltd.
- Orient Fashions Exports Pvt. Ltd.

A total of 282 people participated in the safety training sessions with representation from Factory Management, OHS Committee, HR and Maintenance department and workers from the production area.





January 2021 6 | Issue 1

# **Quarterly Helpline Updates**

In India, one non-LABS, non-zero tolerance Helpline call was received where the caller wanted support on salary-related issues.

# The Vietnam Helpline received 28 non-LABS non-zero tolerance calls:

- Five calls regarding factory policies on job procedure, unilateral contract termination, health insurance, bonuses, and social insurance coverage rate. In these cases, the callers were asked to contact the factories directly.
- Two calls reported familial issues, outside purview of LABS and factory.
- Three callers reported inappropriate attitude of team leader, supervisors, and factory technician respectively. The cases were forward to factory management.
- One caller complained about wage shortage.
- One caller wanted to update her phone number on factory's system.
- One caller complained of productivity-bonus differences between the sewing line's main phase team and supporting team.
- One caller requested installation of a ventilation system in the factory.

- Six callers asked what LABS Helpline is and how it One caller complained about quality of the meals provided by the factory.
  - One caller needed information on their spouse's
  - One caller complained about increased work pressure.
  - Five calls were made in the matter of the 13th-month bonus. One caller reported that factory management ended his contract in December 2020 and asked him to re-apply in January 2021. Two outbound calls were placed to obtain additional information; it was discovered that the factory did ask workers to guit in December 2020 and re-apply as new employees in January 2021 in order to avoid paying the 13th-month bonus. The factory supervisor stated that, since the COVID-19 pandemic, the manager frequently moved workers from one team to another, terminated their labor contracts, and re-recruited those workers as new workers to avoid paying bonuses. Furthermore, the manager did not pay hazardous allowances to those working in chemical-related departments. The case was shared with the Factory as well as the Brand to which the factory supplies.

# **Major Incidents in the Quarter**

- 1. On October 14, 2020, a destructive tornado caused the industrial park in Tien Giang province in Vietnam to collapse. No casualties were reported from the incident.
- 2. On October 8, 2020, fire was reported at a PVC sole-manufacturing unit in Narela in New Delhi, India. No casualties from the incident were reported.
- On November 11, 2020, due to a short circuit, fire erupted in an apparel factory in Faridabad in Haryana, India. Approximately 100 workers were in the factory at the time; fortunately, no casualties were reported. Nonetheless, the factory reported a heavy loss of goods.
- On December 26, 2020, fire broke out at a mask-manufacturing factory in Mayapuri in New Delhi, India which resulted in one death and two injured workers. The factory reported inadequate firefighting preparedness and the authorities stated fire clearance was missing from the factory.

Source: Giadinh.Net, The New Indian Express; Apparel Resources; Economic Times





January 2021 7 | Issue 1

# What the workers are saying



After the factory has been assessed by LABS, we have gained confidence to use and operate the electrical equipment. Safety criteria has improved a lot in the factory.

Ramnath
Electrician - XLNC Fashions



Through the LABS assessment, I realized that there are electrical risks in our factory. I have increased understanding about the LABS electrical standard, which is very helpful for us to improve the working conditions in our factory and to ensure safety for everyone.

**Nguyen Thanh Cong** Electrician, Now Vina Factory (North Vietnam)



# **LABS Secretariat**

Arthur van Schendelstraat 500, 3511 MH Utrecht P.O. Box 1241, 3500 BE Utrecht

LABS is committed to transparency and, along with this newsletter will also publish results regularly on the Website: **www.labsinitiative.com** 

For any questions or comments, please email at: info@labsinitiative.com

## Disclaimer of Liability

The LABS Foundation does not make any representation, warranty, claim or undertaking, express or implied, as to the accuracy, reliability, completeness or reasonableness of the information or content provided in this newsletter. Accordingly, LABS Foundation expressly disclaims liability for errors and omissions in the contents of this newsletter and cannot be held liable for any loss or damage (whether direct, indirect or consequential) suffered by any person as a result of relying on any statement or information contained in or omitted from this newsletter.

## **Copyright Statement**

© 2021 by LABS Foundation. All rights reserved. All content within the LABS newsletters is the property of LABS Foundation unless otherwise stated. No part of the newsletter may be reproduced, transmitted or copied in any form or by any means without the prior written consent of the LABS Foundation.